

REPAIR ESTIMATE

Synthetic document for a portfolio project. Not a real invoice.

Workshop	Ittefaq Autos
Invoice / estimate no.	INV-564226
Date	2026-09-09
Customer	Bilal Javed
Vehicle	Toyota Fortuner (RIR-86-3797)

Item	Amount
Tail Light - replacement / repair parts	PKR 18,200
Labour charges	PKR 13,600
TOTAL	PKR 31,800