

REPAIR ESTIMATE

Synthetic document for a portfolio project. Not a real invoice.

Workshop	Ittefaq Autos
Invoice / estimate no.	INV-804314
Date	2026-04-07
Customer	Usman Mirza
Vehicle	Hyundai Tucson (LE-98-3395)

Item	Amount
Front Tire - replacement / repair parts	PKR 28,200
Labour charges	PKR 29,700
TOTAL	PKR 57,900