

REPAIR ESTIMATE

Synthetic document for a portfolio project. Not a real invoice.

Workshop	Ittefaq Autos
Invoice / estimate no.	INV-181247
Date	2026-09-20
Customer	Tariq Sheikh
Vehicle	Hyundai Tucson (FDA-72-4019)

Item	Amount
Tail Light - replacement / repair parts	PKR 267,200
Labour charges	PKR 330,700
TOTAL	PKR 597,900