

REPAIR ESTIMATE

Synthetic document for a portfolio project. Not a real invoice.

Workshop	Ittefaq Autos
Invoice / estimate no.	INV-835132
Date	2026-09-02
Customer	Bilal Raza
Vehicle	Toyota Fortuner (FDA-38-1135)

Item	Amount
Front Bumper - replacement / repair parts	PKR 18,200
Front Bumper - denting & painting	PKR 4,000
Labour charges	PKR 12,100
TOTAL	PKR 34,300