


9. 3 Wire feeder (high power for 450 A welder)



The repair parts are classified as follows:
A: Consumables or frequently replaced parts
B: Frequently moving parts or mechanical elements
C: Important mechanical elements or electric parts

No.	Description	Part number	Order number	Class	Stock needed	Qty. used	Remarks
1	Motor unit	ADU01721	ADU01721			1	
2	UF base	ADB12002	ADB12002			1	
3	Pressure arm	MDA00004	MDA00004	A	1	1	
4		MDA00005	MDA00005	A	1	1	
5	pressure roller ass'y	MDR00060	MDR00060	A	2	2	
6	Pressure adjust	MDX00008	MDX00008	A	2	2	
7	CC fitting	MFC00011	MFC00011	A	1	1	
9	Feed roller	MDR00055	MDR00055	A	2	2	
10	Feed roller gear	MDG00010	MDG00010	A	2	2	
11	Stainless tube	MGT00011	MGT00011	A	1	1	
12	Center tube	MGW00010	MGW00010	A	1	1	
13	Flexible conduit metal	MGW00016	MGW00016	A	1	1	
14	Conical machine screw	XSS35+16V	YZA95	A	4	4	
-	Feeder cover unit	AKU01235	AKU01235	-	-	1	