A Lemma of the Equilibrium Coefficient

He Entong

1 Introduction

Consider a chemical reaction formula, written as

$$\sum_{i=1}^{N} C_{R_i} R_i \quad \rightleftharpoons \quad \sum_{i=1}^{M} C_{P_i} P_i \tag{1}$$

where R_i , P_i stand for the reactant and product of the reaction, and C_{R_i} , C_{P_i} stand for their coefficient respectively.

According to Van't Hoff's theorem, the equilibrium coefficient of the aforementioned reaction formula is written as

$$\mathcal{K} = \frac{\prod_{i=1}^{M} [P_i]^{C_{P_i}}}{\prod_{i=1}^{N} [R_i]^{C_{R_i}}} \tag{2}$$

In industry production, we are interested that under what circumstance that the conversion percentage of the reactant input is maximized given that the quantity of the reactant is fixed. Without any proof we give the conclusion that

$$\mathcal{K}_{R_{0i}} = ([R_{01}], [R_{02}], [R_{03}] \dots [R_{0N}]), \quad \frac{[R_{0i}]}{C_{R_i}} = Const$$
 (3)

where $[R_{0i}]$ stands for the input density of the i_{th} reactant. Meanwhile the summation of the reactant density is Constant

2 Derivation

We well assume that the input concentration of the reactants is $[R_{0i}]$, the unitary transformation of the chemical reaction is u, which we tend to maximize. Substitute the variables in we obtain

$$[P_i] = C_{P_i} u, [R_i] = [R_{0i}] - C_{R_i} u$$

$$\mathscr{K} = \frac{\prod_{i=1}^{M} (C_{P_i} u)^{C_{P_i}}}{\prod_{i=1}^{N} ([R_{0i}] - C_{R_i} u)^{C_{R_i}}}$$

$$(4)$$

To find u_{max} , we apply the Lagrange Multiplier Method.

The targeted function is $U(u, [R_{01}], [R_{02}], \dots, [R_{0N}]) = u$, and the condition is

$$G(u, [R_{01}], [R_{02}], \dots, [R_{0N}]) = \mathcal{K}\left(\prod_{i=1}^{N} ([R_{0i}] - C_{R_i}u)^{C_{R_i}}\right) - \prod_{i=1}^{M} (C_{P_i}u)^{C_{P_i}} = 0$$

$$H(u, [R_{01}], [R_{02}], \dots, [R_{0N}]) = \sum_{i=1}^{N} [R_{0i}] - Const = 0$$
(5)

Such that

$$\begin{cases}
\frac{\partial U}{\partial u} + \lambda_1 \frac{\partial G}{\partial u} + \lambda_2 \frac{\partial H}{\partial u} = 0 \\
\frac{\partial U}{\partial [R_{0i}]} + \lambda_1 \frac{\partial G}{\partial [R_{0i}]} + \lambda_2 \frac{\partial H}{\partial [R_{0i}]} = 0 \quad i \in (1, 2, 3, \dots N)
\end{cases}$$
(6)

Substitute in we obtain

$$\mathcal{K} \sum_{i=1}^{N} \left[(-C_{R_{i}}^{2})([R_{0i}] - C_{R_{i}}u)^{C_{R_{i}}-1} \prod_{j=1}^{i-1} ([R_{0j}] - C_{R_{j}}u)^{C_{R_{j}}} \prod_{j=i+1}^{N} ([R_{0j}] - C_{R_{j}}u)^{C_{R_{j}}} \right] \\
- \sum_{i=1}^{M} C_{P_{i}}^{2} (C_{P_{i}}u)^{C_{P_{i}}-1} \prod_{j=1}^{i-1} (C_{P_{j}}u)^{C_{P_{j}}} \prod_{j=i+1}^{M} (C_{P_{j}}u)^{C_{P_{j}}} = -\frac{1}{\lambda_{1}}$$

$$\mathcal{K} \left(C_{R_{i}} ([R_{0i}] - C_{R_{i}}u)^{C_{R_{i}}-1} \prod_{j=1}^{i-1} ([R_{0j}] - C_{R_{j}}u)^{C_{R_{j}}} \prod_{j=i+1}^{N} ([R_{0j}] - C_{R_{j}}u)^{C_{R_{j}}} \right) = -\lambda_{2}$$
(7)

The equations above gives us that

$$\frac{C_{R_i}}{[R_{0i}] - C_{R_i} u} = -\frac{\lambda}{\mathscr{K} \left(\prod_{i=1}^{N} ([R_{0i}] - C_{R_i} u)^{C_{R_i}} \right)}$$

$$\frac{[R_{01}]}{C_{R_1}} = \frac{[R_{02}]}{C_{R_2}} = \dots = \frac{[R_{0i}]}{C_{R_i}}$$
(8)

3 Conclusion

Hence, given that the overall quantity of the input reactant is a constant, the conversion percentage reaches the maximum if and only if the input quantity of every reactant is proportional to its stoichiometric coefficients in the chemical reaction formula, respectively, i.e.

$$[R_{0i}] = \sum_{j=1}^{N} [R_{0j}] \left(\frac{C_{R_i}}{\sum_{j=1}^{N} C_{R_j}} \right)$$
(9)