

WORK INSTRUCTION PRJ-2019-0142

Sequence: laser cut -> deburr -> bend -> weld -> paint

Bending: use fixture F-0142, 4 stations

Welding: TIG, back purge on internal corners

QC: dimensional check on door opening  $298 \pm 0.5$  mm