

[ATM-] D – VideoOutputManager
 service binding regression – Completed (→
 Fixed.md) (Phase d / Fix
 c, RECLASSIFIED test-logic bug,
 – – burn-down
 migration)

Status: Completed (→ Fixed.md) — RESOLVED — Phase 30d (Fix #126c). **Was a TEST LOGIC BUG, NOT a product defect. Type:** Task

Original captured evidence: D2 test_all_fixes.sh Phase 4 sub-test B2 reported verbatim:

```
[FAIL] B2: hook fired but VideoOutputManager never bound –
service wiring broken
```

Initial wrong hypothesis: that the framework's MediaCodec.configure hook fires but the bind to the VideoOutputManager AIDL service silently fails — implying real product wiring regression.

Actual root cause (found by Phase 30d systematic-debugging investigation of the MediaCodec.java source):

MediaCodec.java line 2559 emits the
 ATMOSphere: video decoder configure log line UNCONDITIONALLY for every video MIME, BEFORE checking whether VOM has a secondary display, before checking codec name, before checking video dimensions. There are **3 legitimate code paths through the hook where HOOK_HITS fires but registerVideoDecoder is NEVER called by design:**

- (a) vom.hasSecondaryDisplay() == false — emits "ATMOSphere: No secondary display" log, returns early. Correct behavior on no-TV setups.

- (b) `codecName.startsWith("c2.rk.")` — emits "ATMOSphere: Rejecting HW codec" log, sets `forceSwFallback`. ExoPlayer retries with SW codec which DOES reach VOM.
- (c) `minDim < 200` — silent thumbnail filter. Correct behavior.

D2's Phase 4 captured evidence corroborates path (a):

- `WARN: 1.2: Secondary HDMI-A-1 is disconnected (no secondary display)` — D2 had no TV connected
- `B1 PASS: hook fired 2 time(s)` — hook reached line 2559
- `B3 PASS: routing decision logged 2 time(s)` — log went down a routing-decision branch (in this case, "ATMOSphere: No secondary display")
- `B2 FAIL` — bug in the test: it didn't account for the legitimate no-VOM-call branches

Fix #126c (Phase 30d): B2 sub-test in `test_witness_mediacodec_hook.sh` rewritten to grep for `NO_SECONDARY_HITS` ("ATMOSphere: No secondary display" log) and `HW_REJECT_HITS` ("ATMOSphere: Rejecting HW codec" log). Logic flow:

- `VOM_HITS ≥ 1` → PASS (VOM was called).
- `HOOK_HITS ≥ 1 AND NO_SECONDARY_HITS ≥ 1` → SKIP (legitimate no-VOM-call: no TV).
- `HOOK_HITS ≥ 1 AND HW_REJECT_HITS ≥ 1` → SKIP (legitimate no-VOM-call: HW codec → SW fallback retry).
- `HOOK_HITS ≥ 1` (no other branch) → FAIL with refined message "hook reached `registerVideoDecoder` branch but VOM never logged" + diagnostic packet (genuine service-wiring failure case).
- `HOOK_HITS == 0` → SKIP (covered by B1).

Captured-evidence locks against regression: `scripts/testing/test_d11_diagnostic_capture.sh` — 10 invariants now (was 7); pre-build gate `CM-D11-DIAGNOSTIC` covers it; paired mutation in `meta_test_false_positive_proof.sh`.

Lesson learned: the §11.4 covenant cuts both ways. A test that incorrectly fires FAIL on a legitimate code path is itself a §11.4 violation — it produces a false-failure signal that masks real signal AND obscures the device's real working state. The Phase 30d investigation surfaced this exact pattern: D11 looked like a real product

defect but was actually the test framework lying about the device. Systematic debugging (Phase 1 root-cause investigation) found the truth in 30 minutes by tracing the actual code; the wrong-hypothesis Phase 30c diagnostic enhancement would have wasted next cycle's investigation time chasing a non-existent service-wiring bug.

Migration note (2026-05-30, §11.4.19 atomic move): migrated from Issues.md §H region. Type = Task (test-logic correction) → terminal vocab Completed (→ Fixed.md) per §11.4.33. ATM-248 assigned at migration (item had no prior ATM-NNN). Distinct from the Phase 25.4 audit-summary D11 bookkeeping entry (ATM-249) — same legacy "D11" label, different items.
