



ON ENGINE BEING REMOVED
GUN MUST BE RE-TIMED

123-001-001
R-5-001-001
912-111