

HIOKI

AC CLAMP METER
3280-10F, 3280-70F


Rugged & Compact

AC FLEXIBLE
CURRENT SEN-
SOR (option)

φ130 mm (5.12")
4200 A AC

Use with an AC Clamp
Meter to measure
large wires and cur-
rents.

Attachment
(Included with AC Flexible
Current Sensor)



Tip is fixed in an L-shape
for easy manipulation in
confined spaces

AC CLAMP
METER

φ33 mm (1.30")
1000 A AC

₹5190



Pocket size

-25°C to 65°C



Broad operating tem-
perature range

Testers are built tough to
withstand a 1-meter drop
onto a concrete floor



Mechanically
robust design



*AC Flexible Current Sensor optional.
Also available as part of a value-priced set.



Measurement
functions

