

HIOKI

AC CLAMP METER
3280-10F, 3280-70F

Rugged & Compact

AC FLEXIBLE
CURRENT SEN-
SOR (option)

φ130 mm (5.12")
4200 A AC

Use with an AC Clamp
Meter to measure
large wires and cur-
rents.

Attachment
(Included with AC Flexible
Current Sensor)



Tip is fixed in an L-shape
for easy manipulation in
confined spaces

AC CLAMP
METER

φ33 mm (1.30")
1000 A AC

₹5190



Pocket size



-25°C to 65°C

Broad operating tem-
perature range



Testers are built tough to
withstand a 1-meter drop
onto a concrete floor

Mechanically
robust design



*AC Flexible Current Sensor optional.
Also available as part of a value-priced set.



Measurement
functions



Plot No. 126, 1st Floor, Udyog Vihar, Phase-4, Sector-18, Gurgaon 122008, (Haryana)
info@hioki.co.in, ravi@hioki.co.in | 7827978151 / 7838845747