15. In digital multimeter, if we measure higher voltage or current value than the selected range, it shows '1' in the leftmost of the LCD display which means overload. But in ohm's range, '1' denotes ∞ Ω.

16. If it shows 1 in lower range, change the selector switch to the next higher range and measure. Even after the selector switch is opted in the highest range, the meter shows 1, it denotes the component becomes open.

17. For continuous better performance of mutimeter the batteries should be replaced often.

Uses of Multimeter

1. It is used in trouble shooting Radio, TV and all other electronics equipment.
2. It is also used to check electrical appliances.
3. It is used in assembling of electronics equipment.
4. It is used in installation of electronics equipment.
5. It is used to measure AC and DC voltage, current and resistance.

Result

Through this, I came to understand the functions, precautions and uses of analog and digital multimeter.

EE_Practicals_English Version.indd 240 11/10/2020 12:17:45 PM