

Forms of Threads:

1. British Standard Whitworth Thread (BSW)
2. British Association Thread (BA)
3. Metric Thread

British Standard Whitworth Thread (BSW): This form of thread is used as a Standard thread in Britain. It is the modified form of 'V' thread having angle of 55°. British Standard Fine (BSF) and British Standard Pipe (BSP) threads have the same profile of the BSW threads. It is widely used in machine parts. The British Standard threads with fine pitches (B.S.F) are used where more strength is required.




Whitworth Thread Form




British Standard Whitworth Thread

British Association Thread (BA): The angle of BA thread is 47½°. It has fine pitches. This form of thread is generally used at precious instrument like micrometer and vernier caliper, etc… screw having diameters less than ¼ inch.




British Association Thread




British Association Thread

Metric Thread: The angle of metric thread is 60°. It is an Indian Standard Thread and similar to B.S.W thread. This types of thread is mostly used in industries.



Metric Thread



British Metric Thread

Acme Thread: The angle of the thread is 29°. It is modification of square thread. It is stronger than square thread.

BME_Chp07.indd 91 11/9/2020 12:24:37 PM