


Acme Thread


This type of thread is used in lathe lead screws and radial drilling machine etc..,

7.4 KEYS AND KEYWAYS

Keys are machine elements used to connect a shaft and the parts, such as pulleys, gears, couplings etc. so the shaft not only rotates but gears, (or) Flange also rotates which connected with shaft. It is subjected to shearing and torsion stresses, hence it is always made of steel.








Keys and Keyways

MIND MAP



BME_Chp07.indd 92 11/9/2020 12:24:38 PM