Fixture: Fixtures are devices which hold and locate the work during inspection or in a production process. It does not guide the tool.

Important Parts of Fixture

1. Base
2. Setting Block
3. T-Bolt
4. Clamps
5. Locators


Types of Fixtures

1. Vice Jaw Milling Fixtures
2. Plain Milling Fixtures
3. Keyway Milling Fixtures
4. String Milling Fixtures

KEYWAY MILLING FIXTURES

This type of fixture is used to cut the keyway on cylindrical shaft at required place. The cylindrical shaft is mounted on 'V' block and tightened with the help of clamp. At a time, more than one cylindrical work pieces is fitted on this fixture and more than one milling cutter are fixed in milling machine relative to the work piece and then key way operation may be done on cylindrical work piece.


String Milling Fixture: This type of fixture is used to cut slot on the facing side of cylindrical job. Four cylindrical jobs are mounted on four V-blocks at a time in the string Milling fixture. Four slots are cut in facing side of cylindrical jobs by using milling cutters.The milling cutter is mounted with the help of setting block in milling machine.



1. Slot Milling Cutter 2. Work Pieces 3. Base 4. V-Block

String Milling Fixture

TO KNOW HOW TO SET THE CUTTING TOOL IN MACHINE



setting block

7.6 LOCATION AND LOCATORS

When the machining is done, it is necessary to hold and seat, the work piece in correct position on the machine table. The place, where the work piece is tightly fixed by using jigs and fixtures, is called location. The pins which support the work piece are called locators.

BME_Chp07.indd 98 11/9/2020 12:24:40 PM