Disadvantages of gears:

1. They are not suitable for large velocities.
2. They are not suitable for transmitting motion over a large distance.
3. They have no flexibility
4. Gear operation is noisy.

ABSTRACT OF TRANSMISSION OF POWER

1. Methods of transmitting power	1. Belt drive 2. Chain drive 3. Gear drive
2. Transmitting motion of Belt drive	1. Belt Slip 2. Belt are used to distance between the connected shafts is high.
3. Transmitting power, chain and gears	1. No slip in velocity ratio 2. Chains are used to connect small gab between the shafts.
4. Velocity ratio without slips	Positive drive (Chain drive, Gear drive)
5. Velocity ratio with slip	Non – Postive Drive(Belt drive)
6. Shaft which transmits the rotational power is connected with electric motor. pulley	Driving PULLEY
7. Shaft which receives theRotational power is Known as driven shaft and Pulley mounted on it is Known as	FOLLOWER (or) DRIVEN PULLEY
8. The_____ between the Belt and the pulley	Grip
9. Open belt drive	The driver and the follower Rotate in the same direction
10. Cross belt drive	1. The driver and the follower rotate in opposite direction. 2. The grip between the belt and pulley is greater
11. Types of belt	1. Flat belt 2. V–belt
12. The thickness of a flat belt	0.75mm to 5mm
13. The efficiency of the flat belt	98%

GM_Chp09.indd 122 14-02-2019 11:43:58