
Parts of electrical induction motor



Parts of Electrical Induction Motor

Three phase induction motors-the principle of working


When the three phase supply is supplied to three phase windings placed 120° apart inside the stator of an induction motor, a constant rotating magnetic field is induced.

It induces e.m.f in the conductors of the rotor known as armature. According to Lens' law, we know that when an e.m.f is induced in a circuit electromagnetically, the current setup always opposes the motion or change in the current which produces it

Construction of a Induction Motor

The main parts of a induction motor are

1. Stator
2. Rotor.



Construction of a Induction Motor

Stator

It is made of thin sheets arranged as tube. The laminated core has slots cut longitudinally on it parallel to the axis. It is wound for two, four, six, and eight poles depending on the required speed.

GM_Chp10.indd 133 14-02-2019 11:46:21