10. keys are made of
    a) Tungsten b) Steel c) Cast Iron d) Lead
11. If the size of the shaft is smaller than the hole size, the system of fits is
    a) Interference Fit b) Clearance Fit c) Driving Fit d) Push Fit
12. Power is transmitted between shafts at moderate distance by
    a) Belt Drive b) Gear Drive c) Chain Drive d) Friction Drive
13. The unit current is
    a) Volt b) Watt c) Ampere d) Ohm
14. Work study is
    a) Method of plant layout b) A technique of increasing production
    c) Method study d) Work measurement
15. Cost of Accessories which is used to hold and guide the job are
    a) Administrative expenditure. b) Jigs and Fixtures cost.
    c) Workers Wages. d) Cost of raw material.

PART B

Answer any ten questions in not exceeding four lines: **10 × 3 = 30**

16. Who is Machinist?
17. Name five types of files in accordance with the "grade".
18. What are the grade of gauges?
19. What is positive Error in Micrometer ?
20. What are the three kinds of carbon steels?
21. Define "Heat treatment".
22. What are the types of moulding box?
23. Write any three types of Jigs?
24. Write short notes on the types of deviations?
25. What are the types of belt drive?
26. State ohm's law.
27. Define "work measurement".
28. What do you understand about "wages for the workers" ?

PART C

Answer the following questions in about a page. **5 × 5 = 25**

29. Write any five types of vice.
30. A main scale of Vernier caliper is marked in millimeter the Vernier scale
    a) Divisions which is equal to 49 divitions in the main scale what is the least count of that Vernier caliper?
31. Mention the different process of Case hardening?
32. List out any five types of moulding?

GM_BM.indd 162 14-02-2019 12:00:20