T -square are used to draw horizontal lines parallel to each other. When used along with set-square, it is used as a base to draw various angles.

DRAFTER

It comprises of a pair of steel strips hinged at the center .At one end, a clamp is provided . This clamp is useful in clamping the drafter at the left side top corner of the drawing board .The other end is known as working end which consists of the two perpendicular scales and circular base. The perpendicular scales are graduated in millimeters whereas circular scale is graduated in degrees up to 360°.The working end can be oriented to any angle and fixed at the position with help of knob.



When the clamping end is fitted to the drawing board, the working end can be made to slide over the board. After the perpendicular scales are set at the desired angle , parallel or perpendicular lines can be drawn. Taking reference from the circular scale, line at any desired can also be drawn drafter is illustrated in figure.

PENCILS

Pencils are used for making drawings on drawing sheets. The quality of the pencil determines the accuracy and appearance of the drawing. The grades of pencil are designated by marking made on each of them . The grade of pencil describes the hardness of the graphite lead used . The grades of pencil range from 9H to 7B, where 9H is the hardest and 7B is the softest. Hard pencils such as 2H, H are used for making engineering drawing and for lettering and dimensioning , softer pencils like HB pencils are used, also used for making freehand sketches .

