Long chain(Thick)

A long chain line is drawn thick completely for this type of line. The surfaces which are to receive additional treatment are represented by a long chain (thick) line. It is drawn with a HB pencil.

Continuous thin(Wavy)

Irregular boundary lines and short break lines are drawn as wavy continuous thin lines. They are with 2H pencils.

Ruled line and short zigzag(thin)

These lines indicate long break lines. When a long structure of uniform shape is to be shown on a drawing, its view is intercepted by this line and it is drawn with 2H pencil.

