5 SCALE OF DRAWING

INTRODUCTION

It is now our knowledge that drawings are made to show all the details of objects clearly. But, it is not always possible to show the objects on a drawing sheets in actual sizes. For example, large machine parts cannot be represented on a drawing sheet in its original size. Hence, it is necessary to reduce the size of the object in affixed proportion to show it in a drawing. At the same time, it is necessary to increase the size of the object in some cases to give a clear description of the object.

In both cases, a proportion is used either to reduce or increases the dimensions of the object. So the proportion by which the actual size of the object is reduced or increased on a drawing is known as **Scale of a drawing.**

Scales are usually made of celluloid, card board, wood or metal. They are actually rulers on which different proportions are represented to make drawings of objects having different range of dimensions. As far as possible, standard scales are adopted in making drawings. The standard scales are designated asM1, M2, M3 ---------- M8. When standard scales are not suitable for making a particular drawing, scales in required proportion can be constructed.

Uses of Scales

The important uses of scales are

1. Scales are useful in making reduced size and enlarged size drawings.
2. The dimensions of various parts can be measured directly.

Types of Scales

There are three types of scales according to the proportions made on them.

1. Full size scale
2. Reducing scale
3. Enlarging scale