Full size scale

When the dimensions of objects are shown on a drawings in its actual sizes, the scale used in the drawings is full size scale. *Full size scale is indicated as 1:1*

Reducing scale

When the size of the object is too large to be accommodated on a drawing sheet, the dimensions of the object are reduced in a particular proportion and represented in the drawing. This scale is known as reducing scale. Eg :*1:2, 1:5, & 1:10*

Enlarging scale

When the size of the object to be shown on the drawing sheet is very small to give clear description about the object, the dimensions of the object are enlarged in a particular proportion. This scale is called enlarging scale.Eg :*2:1, 5:1, 10:1.*

Full size scale	Reducing scale	Enlarging scale
1:1	1:2 1:5 1:10 1:20 1:50 1:100 1:200	10:1 5:1 2:1