6 PROJECTION

INTRODUCTION

In the introductory chapter, it was explained that the need of the drawing is to communicate the ideas and informations regarding an object between a number of engineers and operators in the field of designing, developing, manufacturing and marketing. As regards to solid geometric drawing, there is the necessity of presenting the informations about a three dimensional object on a two dimensional plane of paper. In overcoming this difficulty, the views of the objects are represented pictorially. Apart from pictorially. Apart from pictorial drawings, the information about the object can be represented in more than one view arranged in a specified order. In general, obtaining the views of the object on a drawing sheet is known as **Projection** and procedures and rules involved in the process are known as **Theory of projection**.

Theory of projection

In the engineering drawing, the exact shape and size of an object should be shown on a two dimensional plane and paper. For doing so, the object is imagined to be located between the observer and the plane on which the view is going to be obtained. Straight lines are drawn from different points on the contour of the object to meet the plane of paper. The points obtained on the sheet of paper are joined in proper sequence to form the image or view of the object.

