7 BLUE PRINT READING

Blueprint is the common name given to the copies taken from an original drawing. The name has nothing to do with the colour of the paper or the colour of the drawing lines.

Blue print reading is an essential skill for any technical persons to perform his job in industry satisfactorily for manufacturing a component accurately and correctly. Proper interpretation of the drawing is essential. Blue print reading involves the following aspects.

1. Visualization of the object from the given orthographic views.
2. Interpretation of the dimensions, notes and symbols.

For blue print reading, one must have a through knowledge of principles of drawing and orthographic projections & also various manufacturing processes.

ABBREVIATIONS FOR MATERIALS

FERROUS MATERIALS		
SI.No.	**Ferrous material**	**Abbreviation**
1	Cast Iron	CI
2	Cast Steel	CS
3	Forged Steel	FS
4	Mild Steel	MS
5	Spring Steel	Sp.S

NON – FERROUS MATERIALS		
SI. No.	**Non – ferrous Material**	**Abbreviation**
1	Aluminium	Al
2	Brass	Br.
3	Bronze	Bronze
4	Copper	cpr
5	Gun Metal	GM
6	White Metal	WM
7	Zinc	Zn