

16. When filling , care is taken that half of the punch mark is retained on the work-piece.
17. The sharp corner of the 'L' shape is filed with the help of triangular file.
18. The edge surface of the workpiece are checked frequently for perpendicularity and parallelism with the help of a try-square.

GIVEN DESIGN OF THE JOB



FINISHED WORKPIECE



Conclusion

The operations of square filing, marking and punching and hacksaw cutting and finish filing (for 'L' shape) are performed according to the given design on the given M.S plate.