

15. The remaining portion of the metal piece is fitted on the bench vice. The rough surface resulting from hacksaw cutting is filed with the help of flat files (rough, medium and smooth)
16. When filing, care is taken that half of the punch mark is retained on the workpiece.
17. The sharp corner of the 'T' shape is filed with the help of triangular file.
18. The edge surfaces of the workpiece are checked frequently for perpendicularity and parallelism with the help of a try- square.

GIVEN DESIGN OF THE JOB



FINISHED WORKPIECE



Conclusion

The operation of square filing, marking, punching hacksaw cutting and finish filing (for 'T' shape) are performed according to the given design on the given M.S plate.