

16. When filing, care is taken that half of the punch mark is retained on the workpiece.
17. The sharp corners of the steps are filed with the help of triangular file.
18. The edge surfaces of the workpiece are checked frequently for perpendicularity and parallelism with the help of a try- square.

GIVEN DESIGN OF THE JOB



FINISHED WORKPIECE



Conclusion

The operation of square filing, marking, punching hacksaw cutting and finish filing (for step cutting) are performed according to the given design on the given M.S plate.