

15. When filing, care is taken that half of the punch mark is retained on the workpiece.
16. The sharp corner of the dovetail cutting (single side) is filed with the help of triangular file.
17. The edge surfaces of the workpiece are checked frequently for perpendicularity and parallelism with the help of a try- square.

GIVEN DESIGN OF THE JOB



FINISHED WORKPIECE



Conclusion :

The operations of square filing, marking, punching hacksaw cutting (for dovetail cutting – single side) are performed according to the given design on the given M.S plate.