4. Not selecting blades of suitable pitch.
5. Poor workmanship.


Reason for the blunting of hacksaw blades

1. The material being cut is harder than the blades.
2. Improper selection of blades.
3. Application of high thrust and speed.
4. Applying thrust during return stroke also
5. Not applying a coolant.

2.8 BEARING PULLER

This is a device to remove the bearing from the shaft. It works in the principle of bench-vice. The legs of the puller is widened to hold the bearing and the bottom of the screws of the puller, should touch the face of the shaft, then turned clockwise as shown in the figure. Due to the movement of the screw rod of the puller the bearings is easily pulled out from the shaft. Arbor press is used to fix the bearing in the shafts.






2D and 3D View of Bearing Puller
1. Bearing 2. Shaft 3. Leg 4. Screw 5. Handle

2.9 SCRAPER

Scrapers are used for sharing off or parting off thin slices or flakes of metal to make a fine smooth surface. The materials used for making scrapers is a good quality forged steel and the cutting edge is very hard. Scraping is a process of obtaining a true flat surface which is superior in quality than that can be produced by machining are filing. The top of the surface plate is coated with a thin film of Prussian blue the surface to be scraped is laid on the surface plate and moved back and forth. The high



Types of Scraper

BME_Chp02.indd 21 11/9/2020 12:17:28 PM