5. Scriber
6. Surface Plate
7. Marking Table
8. Surface Gauge
9. V - Block
10. Angle Plate

STEEL RULE




Steel Rule

Steel rule is used generally for measuring all kinds of objects. It is also adopted for making and scribing straight lines. It is made of thin steel sheet and hence named so.

DIVIDER

Divider has got two legs having sharpened ends. The two legs are connected at the top by a rivet or by a spring.



Divider

Uses of Divider

1. To scribe arcs and parallel lines on work pieces.
2. To divide straight lines and curved lines into equal parts.
3. To find and check the centre of a round rod.
4. To mark correct dimensions taken from the steel rule on work pieces.

2.11 PUNCHES

Punches are used to make permanent marks on the lines already scribed on the work pieces. The punch marks make the line appear clearly. Punches are also used to make marks on exact locations on the work pieces where drilling is to be performed.



Punch

Punches are made of steel alloys. The punching ends are ground to be a required angle. The body of the punch is knurled to provide gripness.

Types of punches

1. Centre Punch
2. Dot Punch
3. Prick Punch
4. Bell Punch
5. Hollow Punch
6. Pin Punch

CENTRE PUNCH

The angle of the centre punch is 90°. It is used to make marks on the locations, where drilling operations is going to be performed. The marks made by the punches will allow the drill to get seated and rotated at the exact location.



Centre Punch

BME_Chp02.indd 23 11/9/2020 12:17:28 PM