
2.12 SCRIBER

A scriber is used to scribe lines on the work pieces it is made of high carbon steel, which is hardened and tempered. The end of the scriber is ground sharp to have an angle of 12° to 15°. The body of the scriber is knurled to provide gripness. It is available in different lengths 150mm, 200mm & 250mm.

There are different types of scribers available. They are,

1. Straight ended Scriber
2. Bent ended Scriber
3. Adjustable Scriber
4. Offset Scriber
5. Knife edge Scriber.



Types of Scriber





Surface plate is invented by "Hendry Maudslay". He was called as "Father of Machine Tool Technology"

Maintenance of Scribers

1. The point of the scriber should be maintained straight and sharp.
2. Heavy materials should not be placed on it.
3. The scriber point should be kept in a cover which not in use.
4. Scriber should be used after cleaning of moulded area.

SURFACE PLATE

The flatness of a surface of a work can be tested with the help of a surface plate. It is also used for marking-out work.



Surface Plate

Surface plates are made of grey cast iron. The top surface of the surface plate is very accurately machined and scraped for further accuracy. It should be mounted on a bench or on a special stand at an height of about 800mm. They are made in two grades of accuracy A grade and B grade. A grade surface plates are with 0.005mm flatness and B grade with 0.2 mm flatness. It is available in sizes of 150 x 100 mm and 1000 x 750mm care of surface plates

1. The surface plate should be covered when not in use.
2. The top surface should be kept free from rust and dirt.
3. It should be wiped with a clean cloth and smeared with grease or oil after use.
4. Parts having burrs on them should not be rubbed on the top surface of the plate.

BME_Chp02.indd 25 11/9/2020 12:17:29 PM