Maintenance of Scales

1. Scales should not be used as wedge or Screw driver.
2. Heavy objects should not be placed on it.
3. Scales should not be used for rough surface.

3.3 CALIPERS

A caliper can be as simple as a compass with inward or outward - facing points. Calipers are used to measure diameters of round circular and objects internal and external dimensions of square or rectangular objects. It does not show the measurements directly, but along with steel rule, They are also used to measure dimensions rotating of and hotter jobs.

Types of Calipers

1. Outside Caliper
2. Inside Caliper
3. Jenny C aliper

Outside Caliper

Outside Caliper is used to measure external dimensions like length and breadth of various objects and diameters of round rods.

Inside Caliper

Inside caliper is used to measure the internal diameter of hole and length of grooving and undercutting of cylindrical jobs.

Jenny Caliper

Jenny caliper is used to find the center of facing side of round rod and to draw parallel lines on work pieces. One of the legs of this type of caliper is straight and other is bent.


The above calipers' legs are generally joined by either Rivet or Spring.

Rivet Type

The two legs of this type of calipers are connected by rivets at the top. So these type of calipers are called as "RIVET TYPE CALIPERS'

Spring Type

The two legs of this type of caliper are connected by springs at the top. So these



Outside Caliper | Inside Caliper | Inside Caliper Spring Type | Jenny Caliper

GM_Chp03.indd 36 14-02-2019 11:33:15