



1. Base	**6. Fine Adjustment Clamp**
2. Column	**7. Scriber**
3. Slide	**8. Clamp**
4. Slide Clamp	**9. Fine Adjustment**
5. Vernier Scale	**10. Main Scale**



Vernier Height Gauge


A Graduated main scale is mounted vertically on the base. A movable Vernier scale is fixed on main scale and slides over the fixed on main scale and slider over the main scale up and down. A scriber is fitted to Vernier scale. A clamping screw is fitted on Vernier scale to lock the Vernier scale at the required height.


There is a fine adjusting slide fitted on the Vernier scale to with screw which is useful in adjusting the vernier scale accurately. Measurements are made by placing the Vernier height gauge on their surface plate. Opposite to this, objects may be placed in Angle plate.

3.5 MICROMETER

The Micrometer is an extremely precise measuring instrument. It is used to measure length width and thickness of small and medium sized objects and diameter of wires and small rods, to an accuracy of 0.01mm in metric scale and 0.001 inches in British scale. The instrument used measure outside dimensions of objects this micrometer is also called as outside micrometer.

The frame is 'U' Shaped and it is made up of steel. The hardened Anvil is attached to left end of the frame. A graduated barrel having internal thread is called as 'sleeve'. It is attached to the right end of 'U' frame. It is the "Main Scale".





Line Diagram and 3D of Micrometer

The spindle is attached to the thimble and the rotation of thimble will make the spindle to move forward or backward. The beveled edge of the thimble is graduated and called as thimble scale. A ratchet stop' is attached to thimble. It gives 'Click sound when we give more pressure to rotate

GM_Chp03.indd 39 14-02-2019 11:33:17