



Annealing Process



Normalizing Chart





Harry Brearley was an English metallurgist, usually credited with the invention of "rustless steel".

NORMALIZING

Normalizing is a process in which a steel is heated above the critical temperature, holding for a period of time, and allowed to cool by air. The transformation of Internal structure are occurred during the cooling process.

After forging, rolling and casting, the steel parts are distorted in its structure. In this case, Normalizing is done to rectify the internal structure of the parts to its original position.

Process of Normalizing

1. In this process the steel is heat to 50°C above the higher critical temperature. Holding it at that temperature for approximately 15 minutes.
2. Cooling it in air.

Purpose of Normalizing

1. To refine the grain size
2. To remove internal stresses
3. To improve machinability
4. To improve strength
5. For homogeneous structure

HARDENING

This process makes the material stronger. In the process of hardening, the

GM_Chp05.indd 65 14-02-2019 11:39:00