


Sintering furnace

5.6 HEAT TREATMENT FURNACES

Some common types of heat treatment furnaces are mentioned below

1. Sintering Furnace
2. Oil fired Furnace
3. Gas fired Furnace
4. Salt bath Furnace

ELECTRIC FURNACE:

Materials to be heated, using electrical equipments are called electric furnace.

SINTERING FURNACE:

Sintering furnace is one of the electric furnace. In this furnace, there are three zones, namely heating zone, soaking zone and cooling zone. Heat is controlled by thermostat and the temperature is measured by thermo couple. Component is placed in the tray which is passed through the furnace by means of iron belt conveyers.

The component is heated in the heating zone, then it is maintained at the sintering temperature in the soaking zone. Finally the component is cooled in the cooling zone. In this process operating, increasing and decreasing of the Iron belt conveyers is controlled by the controlling unit.

Glossary

1. Annealing – மிருதுவாக்குதல்
2. Hardening – கடினப்படுத்துதல்
3. Case Hardening – புறக் கடினமாக்கல்
4. Quenching – விரைவாக குளிரச்செய்தல்
5. Sintering Furnace – மின்சார உலை

GM_Chp05.indd 70 14-02-2019 11:39:02