PART A

Mark 1

STX1G3

Choose the Correct Answer:

1. Initially the emf generated is an alternating one. But this alternating emf is converted into direct emf by
   a) Slip-ring
   b) Commutator
   c) Carbon brush
   d) End rings

2. The direction of induced emf in DC generator is found by
   a) Fleming's left-hand rule
   b) Fleming's Right-hand rule
   c) Faraday's law
   d) Kirchhoff's law

3. The Yoke of a DC machine is made up of
   a) Copper
   b) Aluminium
   c) Zinc
   d) Cast-iron

4. Which of the following is a function of brushes?
   a) To convert AC to DC
   b) To convert DC to AC
   c) To collect the current and to deliver to load
   d) None of the above

5. The armature is made up of
   a) Solid aluminium
   b) Solid steel
   c) Laminated aluminium
   d) Laminated steel

6. The principle DC motor is based on
   a) Fleming's left-hand rule
   b) Fleming's Right-hand rule
   c) Faraday's law
   d) None

7. For electric traction, the motor used is
   a) DC shunt motor
   b) DC series motor
   c) DC compound motor
   d) AC motor

8. Which of the following motor is constant speed motor?
   a) DC shunt motor
   b) DC series motor
   c) AC series motor
   d) None

9. DC compound motor is having …… winding
   a) series winding only
   b) shunt winding only
   c) series or shunt winding only
   d) series and shunt winding only

10. Commutator is made up of ----------
    a) Copper
    b) Brass
    c) Aluminium
    d) Silver

EMA_English_Chp07.indd 119 10-02-2019 13:27:19