Q A

PART A

SUAJ6M

Mark 1

Choose the Correct Answer:

1. The AC generator is also called as
   i) Alternator
   ii) DC generator
   iii) Synchronous motor
   iv) Synchronous generator
   (a) (i) and (ii) only
   (b) (i) and (iii) Only
   (c) (i) and (iv) only
   (d) (ii) and (iii) only

2. Armature Core is laminated
   a) To reduce hysteresis loss
   b) To reduce eddy current loss
   c) To reduce copper loss
   d) To reduce mechanical losses

3. Slot types in the stator core of an alternator are
   a) Wide – open slots
   b) Semi – closed slots
   c) Closed slots
   d) All of the above

4. Which type of rotor is used in low and medium speed alternators?
   a) Salient – pole type rotor
   b) Cylindrical type rotor
   c) Squirrel cage type rotor
   d) None of the above

5. Size of stator of an alternator is small in diameter and large in axial length, is called as
   a) Salient – pole type alternators
   b) Turbo alternators
   c) D.C. generator
   d) None of the above

6. Which type of rotors isused for very high speed in alternators?
   a) Salient pole type
   b) Smooth cylindrical type
   c) Squirrel cage type
   d) None of the above

7. Axial Ventilating holes are provided to
   a) Increase eddy current
   b) Increase cooling effect
   c) Reduce eddy current
   d) Reduce cooling effect

8. Stationary field and rotating armature type is used in
   i) Small size generators
   ii) For low voltages
   iii) Large size generators
   iv) For high voltages
   (a) (i) and (ii)
   (b) (ii) and (iii)
   (c) (iii) and (iv)
   (d) (iv) and (i)

EMA_English_Chp08.indd 136 11/9/2020 3:24:22 PM