7. Under faulty conditions, the appliances in houses must be checked and ensure that the equipment is disconnected from the supply.
   Example:- Fan, Grinder, Mixie etc.
8. If fire occurs in the electrical circuit, the main switch is turned OFF immediately. For extinguishing electric fire, use of carbon-di-oxide extinguisher or dry powder extinguisher is advised.
   (Water should not be used to extinguish electric fire because it conducts electricity and will cause severe accident.)
9. If any person gets electric shock by touching the electric wire, the supply should be disconnected immediately. The person must be removed from the wire using dry stick, drywooden plank or dry cloth.
10. Sweating hand should not be used to switch ON or work on the electric supply. If the person has sweating on the hand continuously, he must wear gloves.

1.4 ELECTRIC SHOCK

Human body has a electrical conducting property. Without sweating the resistance of human body is approximately 80000Ω (ohm) and during sweating, resistance of the human body is approximately 1000Ω (ohm). If we touch any current carrying conductor, the current is conducted through our body to earth and we get electric shock more over nervous structure, heart, lungs, and brain can also be affected. If the current is heavy, even death may occur. Therefore, we must know, even though current is essential, if it is used wrongly, it will cause heavy loss i.e death and economical loss.

To prevent such electrical shocks, we must know about the preventive measures and protective measures for safety precautions.

1.5 PREVENTIVE MEASURES TO AVOID ELECTRIC SHOCK

Some of the methods employed to avoid electric shock are listed below:

- The operation of electrical equipment must be clearly known.
- Damaged wire should not be used for wiring or electrical connection.
- The electrical instruments used for connection (i.e switch, plug, pushing etc). It should not have any scratch or break.
- The hand tools should be properly insulated.
- Proper earthing should be provided.
- For any reason, do not operate by overcoming the safety rules.

1.6 FIRST AID

When a man gets affected by an electrical shock in an unavoidable condition, he must be given first aid before taking to the hospital.

When a person is affected by current shock, the circuit should be disconnected first. If the main switch is nearer, put off the switch. Using any wooden stick, we could disconnect the person from the circuit. Then immediately take him to hospital.

If the affected person loses consciousness, but breathes normally, then

EMA_English_Chp01.indd 7 12/17/2019 4:42:43 PM