








Step 1. Select the switch of the multimeter in resistance mode

Step2. Connect the positive terminal of the diode to Anode and the negative terminal to the cathode.

Step3. Check the reading of the multimeter.

Under this condition the resistance of the diode is very less that means good conduction is expected.

EMA_English_Practical.indd 233 11/9/2020 3:56:19 PM