Testing of Capacitor

Objective: To test the condition of a capacitor.

Test & Check a Capacitor By a Digital Multimeter

1. Make sure the capacitor is discharged.
2. Set the meter on Ohm range (Set it at least 1000 Ohm = 1k).
3. Connect the meter leads to the capacitor terminals.
4. Digital meter will show some numbers for a second. Note the reading.
5. And then immediately it will return to the OL (Open Line). Every attempt of Step 2 will show the same result as was in step 4 and Step 5. It means that Capacitor is in Good Condition.
6. If there is Change, then Capacitor is dead.



Conclusion

Thus the passive elements of electrical engineering is tested for its values.

Result

In this practical, I have known the method of testing the value of Resistor, Diode, Transistor and Capacitor.

EMA_English_Practical.indd 236 11/9/2020 3:56:20 PM