

2. **Hidden Lines (or) Dotted Lines:** These lines are used to show the hidden planes and hidden edges of an object. The length of this line may be 2mm to 3mm. The interval between the lines should be 1mm. The point of intersection of these lines with the outlines (or) another hidden line should be clearly shown.
3. **Centre Line**: The centre point of arc, circle are denoted by this line. The axes of symmetrical geometrical objects like cylinder sphere and cone are denoted by this line. Construction of this line is with uniform interval of alternative lengthy line and small line. Interval is 1mm length of the line is 9 to 12mm and small lines in 1.5mm
4. **Dimension Line (D.L)** This line is a continuous narrow line drawn parallel to the edge or surface whose measurement should be shown. It should be placed outside the view. Sometimes in unavoidable situation it may be placed inside the view.




Dimension line is placed at least 12 mm away from the outline of the drawing. It is terminated by arrows at its end.

5. **Arrow Heads**: At both ends of the dimension line, the arrows are marked. Arrow marks are drawn as per the sketch shown. But same type of arrow mark should be used in a sketch .The angle between the arrow mark may be 15° to 90°.

Where space is too small for an arrowhead, the oblique stroke (drawn as a short line inclined at an angle of 45°) or a dot may be substituted as shown in fig.



6. **Extension Line (or) Projection Line:** It is a continuous narrow line drawn perpendicular to the outline to be dimensioned and without leaving a gap from the portion. It is drawn extending slightly beyond the dimension line about 2mm.



7. **Leader Line:**

Leader line is a continuous narrow line, connecting dimensional value or

Civil_English_Unit_1.indd 16 12/21/2019 1:06:37 PM