3	A circle should be dimension by its diameter using the symbol Ø.		
4	Dimensions to the hidden lines of a view should be avioded.		
5	Arrange a chain of dimensions in a continuos line.		
6	Larger dimensions should be placed out side the shorter one.		
7	Overall dimension should be placed out side of the intermediate dimensions.		
8	Dimension figures should be approximately centered between the arrow heads.		

Civil_English_Unit_1.indd 20 12/21/2019 1:06:39 PM