



ACTIVITY 1


Draw some circles using circle command and take print outs.

2.2.2.4 Rectangle



There are two dimensional measurements available for rectangle such as length and breadth (or) length and depth. When we are drawing by AutoCAD, we are not using these measurements. Instead of measurements, the rectangle is drawn with diagonal.


We have to give the values of lower edge of left side and opposite corner of the rectangle. Two corners are noted as first corner and other corner respectively.



ACTIVITY 2

Draw some rectangles in various sizes and take print outs.

2.2.2.5 Arc



Part of a circumference of a circle is called as an arc. It is curved in shape. Three points are required to draw an arc. We can also draw the arc with the centre point of arc, angle of arc and radius of arc. There are six methods to draw an arc.

Civil_English_Unit_2.indd 36 12/21/2019 1:58:18 PM