

are drawn in one side. Then the cursor is moved to left axis and lines are drawn in another side. Like this upside lines are drawn by moving to vertical axis.





When isometric drawing is drawn the axes are changed and planes are drawn parallel to that axis. These are called isometric plane.


So, Isometric drawings are drawn with three planes of right side plane, left side plane and top plane.




2.2.10 Orthographic View









Orthographic views are multiple views of a single object. It is a two dimensional drawing of three dimensional object using two or more additional views of the object in the 3 axes. (x, y and z)

Civil_English_Unit_2.indd 51 12/21/2019 1:58:24 PM