



Figure 1.2(a) Wear Fit Cloths in Self-Safety

10. Avoid having food, chats in the workplace.
11. Ensure proper lighting and ventilation at the workplace.
12. Don't work with illness.

1.3 SAFETY PRECAUTION IN MACHINES

The following are the safety rules to be followed before the process, during the process and after the process. Refer Figures 1.3, 1.3(a) and 1.3(b).

1. Don't lean on the machine during its working.
2. Operate the machine after ensuring the working condition of the machine.
3. Equipment should be used with proper safety guards, especially for rotating parts.
4. Ensure proper grease and lubrication oil before the start of any operation.
5. Stop the machine, if an unusual sound is heard.
6. Lubrication should be made periodically.

AM_Unit_01.indd 4 12/20/2019 4:19:08 PM