Grinder Safety (cont)




Figure 1.3 (b) Safety Precaution in Machines

1.4 SAFETY PRECAUTION IN USING TOOLS

Hand tools are a common part of our daily work lives. Hand tools like Hammers, wrenches, chisels, pliers, screwdrivers etc., may look harmless, but they are the cause of many injuries. These injuries can be serious, including loss of fingers or eyesight. Hence proper safety measure should be taken while in use. Refer Figures 1.4 and 1.4(a).

1. Use files, chisels or other hand tools with proper handle.
2. Use appropriate coolants during cutting operation.
3. Keep the sharp tools securely in their protective covers before and after use.
4. Select and Use the right tool for the job. Substitutes increase the chance of having an accident. For example, Don't use a wrench as a hammer, screwdriver as a chisel, file as lever etc.,
5. Don't over tight the hacksaw blade.
6. Always provide training on how to choose the right tool for the job, how to correctly use each tool, and how to identify when tools need repair.
7. Use good quality tools and Keep tools in good condition at all times. Inspect tools for defects before use. Replace or repair defective tools.
8. Carry tools in a sturdy toolbox to and from the worksite.
9. Wear safety glasses or goggles, or a faceshield (with safety glasses or goggles)



Figure 1.4 Safety Precaution in Using Tools

AM_Unit_01.indd 6 12/20/2019 4:19:10 PM