Rapid wear on fan belt:

Causes	Remedies
1. Belt may be under over tight	Has to be adjusted for exact tension.
2. Belt may be affixed with improper length.	The belt that is recommended by the manufacturer has to be used.
3. There may be a deposition of oil or grease in the belt.	Clean the belt with petrol and fix it.
4. Belt may not be fixed properly to the pulley.	Affix the belt properly on the pulley.

Over noise from radiator fan:

Causes	Remedies
1. Fan belt may be fixed with heavy tight.	Has to be adjusted for exact tension.
2. Fan belt may be worn out.	Has to be changed with a new one.
3. Fan pulley may be loosened.	Has to be tightened.
4. There may be high amount of ply in the water pump shaft.	Has to be adjusted for correct scale of ply.
5. Fan blades may be expanded.	Have to be changed with a new fan.
6. Water pump pulley may leave its position and hanged on the radiators body.	Has to be checked and repaired.

Student Activity

I. Students have to follow the following safety precautions:

1. Students should visit the nearby workshops to study the process of engine cooling with external fins and should have a hands-on experience on engine dismantling and assembling.
2. Students should visit the nearby workshops to study the process of cooling engines with water and should a report with the sketch of radiator tank, water pump and thermostat valve.

AM_Unit_07.indd 154 31-01-2019 17:50:51