Over cooling	
a) Thermostat may be damaged	To be replaced
b) Not working of temperature gauge	To be replaced

10.4.2 Lubrication System

Sl. No.	Complaint	Causes	Remedy
1.	Oil Leakage	a) Gasket damaged b) Spraying excess	To be replaced Excess oil to be removed through drainage plug
2.	Low Oil	a) Oil level may be low b) Blocks in the oil filter c) Relief valve springs tension may be low d) Oil diluted oil may be thinned e) Oil gauge may be damaged	Fill correct level Replace the filter element Change the defective spring Change correct grade oil To be replaced
3.	Excessive oil con-sumption	a) Damaging of Piston, piston rings, cylinder liner b) Valve seat defective c) Damaging of Valve stem d) Oil leakage e) Excess Oil level f) Using low viscosity oil	To be replaced To be replaced To be replaced To be change the gasket Maintain the oil level Use correct viscosity oil
4.	High oil pressure	a) Blocks in oil pipe b) Damaged the pressure parts c) High viscosity oil	To be removed the blocks pipe to be reload or clear To be change / rectify Use correct viscosity oil

AM_Unit_10.indd 209 31-01-2019 18:04:27