



Figure 2.3.1(b) Outside Micrometer

c) Vernier Caliper

Vernier calliper is often used in factories as it is easy and convenient to measure metal components than micrometers. It helps to measure external and internal levels. It is a direct measuring instrument. Vernier Caliper is shows in Fig 2.3.1(c).






Figure 2.3.1(c) Vernier Caliper

d) Wire Gauge

The thickness of the thin wire or the plate is represented by the gauge number. If the gauge number is higher, the thickness

AM_Unit_02.indd 36 12/20/2019 4:25:27 PM