

Bureau of Indian Standards

The Bureau of Indian Standards (BIS) is the national Standards Body of India working under the aegis of Ministry of Consumer Affairs, Food & Public Distribution, Government of India.

It is established by the Bureau of Indian Standards Act, 1986 which came into effect on 23 December 1986.

The Minister in charge of the Ministry or Department having administrative control of the BIS is the ex-officio President of the BIS.

The organisation was formerly the Indian Standards Institution (ISI), set up under the Resolution of the then Department of Industries and Supplies No. 1 Std.(4)/45, dated 3 September 1946. The ISI was registered under the Societies Registration Act, 1860.

As a corporate body, it has 25 members drawn from Central or State Governments, industry, scientific and research institutions, and consumer organisations.

Its headquarters are in New Delhi, with regional offices in Kolkata, Chennai, Mumbai, Chandigarh and Delhi and 20 branch offices. It also works as WTO-TBT enquiry point for India.

Construction

Its shaft is made of with cast iron material. By keeping the gravitational nature in mind, the jack basement is designed. The top portion of the main shell fixed with rotating block. Rotating block consists of with holes through which the handles are fixed and we can rotate it freely. A support is attached to the square thread rod.

Function

At first, screw jack has to be placed below the lifted component. Depends on the nature of the soil and the requirement of height to be lifted, it has been supported by the wooden sleeper. Then by fixing the handle on the holes in the rotating block and rotating the handle, the vehicle will be lifted to the required height and work under the vehicle will be carried out. After finishing the work, again by rotating the handle in anti-clockwise direction vehicle will be grounded.

Capacity

Screw jack capacity is mentioned by maximum weight it can withstand. It is specified in terms of tonnage. It has to be lifted based on the given specification. If it is operated to lift more load than the specification, then severe damages will occur. Lubrication should be properly done to the moving and rotating parts.

AM_Unit_02.indd 47 12/20/2019 4:25:30 PM